

Community centre electrical findings

- | | |
|---------------------|------|
| 1. Red to Neutral | 320v |
| 2. White to Neutral | 105v |
| 3. Blue to Neutral | 105v |
| 4. Red to White | 400v |
| 5. Red to Blue | 400v |
| 6. White to Blue | 0 v |
| 7. Red alone | 21 v |
| 8. White alone | 9 v |
| 9. Blue alone | 9 v |

Eskom point of supply to community centre

- | | |
|----------------------|-------|
| 1. Red to yellow | 405 v |
| 2. Red to blue | 403 v |
| 3. Yellow to Blue | 400 v |
| 4. Red to Neutral | 330 v |
| 5. Yellow to neutral | 330 v |
| 6. Blue to neutral | 70 v |

Kindly not appliances and equipment has been damaged due to the voltage discrepancy and this needs urgent attention